

Storm Water Construction General Permit Inspection Report

RWQCB - Region 5S

WDID # 5S03C337319

County: Amador

Del Rapini Const Inc

Pine Grove Bluffs

Owner's Name

Name of Development

28555 Rollins Lake Rd

Owner's Street Address

Developer Contact and Phone NC #

Colfax, CA 95713

Ridge Road & Hwy 88

Owner's City, State and Zip code

Site Address

Del Rapini 530-389-8002

Pine Grove, CA 95665

Owner's contact person and phone #

Site City, State, and Zip Code

Rich Muhl

2/23/2009

Samples taken 7:20 AM

Inspection Conducted By

Date of Inspection

Time of Inspection

Dry Hot Clear Overcast X Cold Raining X

Weather Conditions During Inspection (circle all that apply)

Status of Construction

Type of Inspection:

Inspection in Conjunction with Other Permit

Permit Type: Construction

X

Termination Request

Compliance Inspection

Outreach Inspection

Discharger/Facility Request

Follow-up to previous inspection ** Date of Previous Inspection

Other

Control Measures Checklist:

Yes - Evident on inspection

No - Non evident on inspection

Areas of Concern:

Yes

No

Evidence of erosion?

X

(hills, gullies, slips)

Dirt/sediment tracked in streets?

X

Evidence of dewatering?

X

Other

The SWPPP was not reviewed

Storm Water Samples Collected?

X

Yes

No

Non-Storm Water Discharge or Evidence

of Non-Storm Water Discharge Observed?

Yes

X

Separate Inspection Report Written?

Yes

No

Updated SWPPP on Site?

X

Yes

No

Inspection Summary (complete only if no separate inspection report is written):

During the site inspection staff observed significant storm water management problems on the construction site. The inspection was conducted just after a significant rain event that had occurred the previous day and throughout the night. Light rain was falling during the site inspection. The entire site was again walked and staff observed no significant improvement to the BMPs since the site inspection the previous day. Staff again observed a turbid storm water discharge from both outfall areas. The western outfall location was sampled and flow was measured in the discharge channel. Using a field turbidity meter the turbidity was 384 NTUs at the outfall location. Jackson Creek was also sampled upstream of the construction site using a field turbidity meter and the turbidity level was 30 NTUs (see inspection photographs).

Signature

Inspection ID: 1639394

Enrollment ID: 362788

Violation ID(A): 811389

Violation ID (B): 811390

Date Entered: 3/20/2009

Entered By: JIC

Senior Review: JIM

2/23/09



Figure 1: Turbid storm water discharging from the construction site



Figure 2: View of the western discharge location



Figure 3: Another view of the western discharge location



Figure 4: Turbid storm water flowing into the western culvert which discharges into Jackson Creek



Figure 5: Sample location



Figure 6: Area above the western discharge location where staff observed no effective storm water management BMPs

2/23/09



Figure 7: Area directly below the area shown in Figure 6



Figure 8: Same area Note: the general lack of BMPs on the slope



Figure 9: Area above the discharge location in Figure 8 Note: the lack of erosion control BMPs



Figure 10: View of the same area



Figure 11: General lack of BMPs above the area in Figure 9



Figure 12: Lack of an effective combination of erosion and sediment control BMPs

2/23/09



Figure 13: Lack of an effective combination of erosion and sediment control BMPs



Figure 14: Poorly stabilized stockpile



Figure 15: Lack of an effective combination of erosion and sediment control BMPs



Figure 16: Lack of an effective combination of erosion and sediment control BMPs prior to one of the discharge locations



Figure 17: Fiber rolls installed prior to turbid stormwater discharge into the down drain



Figure 18: Another view of the fiber rolls installed prior to discharge into the down drain



Figure 19: Poorly protected slope



Figure 20: Lack of an effective combination of erosion and sediment control BMPs Note: the discharge into the down drain and the lack of effective BMPs prior to the down drain



Figure 21: Lack of an effective combination of erosion and sediment control BMPs



Figure 22: Turbid storm water ponded onsite



Figure 23: Another view of the same area Note: the general lack of erosion control BMPs



Figure 24: Lack of an effective combination of erosion and sediment control BMPs

2/23/09



Figure 25: Lack of an effective combination of erosion and sediment control BMPs Note: the only BMP installed is a fiber roll



Figure 26: Another view of the same area Note: the lack of erosion control BMPs



Figure 27: Light application of straw mulch along Ridge Road



Figure 28: Sediment laden storm water flowing down to the drain inlet adjacent to Ridge Road



Figure 29: Turbid storm water flowing into the drain inlet along Ridge Road



Figure 30: Another view of the drain inlet along Ridge Road

2/23/09



Figure 31: Another view of the area just above the drain inlet on Ridge Road



Figure 32: Lack of an effective combination of erosion and sediment control BMPs